SERVICE BULLETIN: UPDATED DEEMAXX CALIPER BOLT TORQUE

DeeMaxx Components, one of TRP's strategic partners, issued a service bulletin on October 7 that changes the torque specification for DeeMaxx caliper bolts.

If you install or service DeeMaxx disc brakes, please pass this along to your installers and service technicians.

DEEMAXX COMPONENTS SERVICE BULLETIN

Updated Caliper Bolt Torque Specifications

Date: October 7, 2026 • **Effective:** Immediately

PREVIOUS SPECIFICATION	NEW SPECIFICATION
40 ft-lb	50 ft-lb

Effective immediately, 3-6K, 7-8K and 10-12K caliper bolts should be tightened to 50 ft-lb during installation, reassembly or service.

Reason for the update

As part of its ongoing engineering review, product testing and continuous improvement program, DeeMaxx periodically evaluates its installation and service specifications. Based on that evaluation, DeeMaxx has revised the recommended torque specification from 40 ft-lb to 50 ft-lb for 3-6K, 7-8K and 10-12K caliper bolts.

Installers and service technicians should update their records and use the revised specification going forward.

Important

Always follow the latest DeeMaxx installation instructions and service specifications for the specific brake system and component being serviced.

Questions about this bulletin or DeeMaxx installation specifications? Call DeeMaxx technical support at **682-200-6003**.

DeeMaxx calipers, pads and complete kits

TRP carries DeeMaxx calipers, replacement pads and complete disc brake kits. You'll find them in our Disc Brake Catalog.

Download the Disc Brake Catalog

ELKHART DISTRIBUTION & SALES
574-389-9941

DALLAS DISTRIBUTION & SALES
972-279-9863

For pricing and availability on DeeMaxx disc brake parts, contact your TRP Account Executive: